

BK
TOM MEERSCHAERT

AUTO OWNERS
ADJUSTER: TYLER CHESLEY
CHESLEY.TYLER@ADINS.COM
1-5-19
(989) 287-1858


1/5/19

BK # 6991 EDMORE, MI
CLAIM # 300-356095-2018
CAR ACCIDENT REPAIR

MATERIALS NEEDED:
FROM GPS HOSPITALITY

- SILL (10')
- WAINSCOT
- BRICK
- PAINT
- TILE

INTERIOR



- 6'-8' OF SILL
- 2 SHEETS 3/4" DRYWALL
- REMOVE PEDESTAL TABLE & BOOTHS
- REMOVE WAINSCOT (31" H X 10')
- REMOVE DRYWALL
- REMOVE BROKEN SILL
- INSPECT TILE BASE AND REPLACE AS NECESSARY
- REMOVE/REPLACE WINDOW CHANNEL & WINDOW

- REMOVE/REPLACE CORNER PIECE
- REMOVE/REPLACE HEADER ABOVE WINDOW
- CAULK & PAINT INTERIOR AROUND WINDOW

EXTERIOR

