



Client: PSI/Intertek

Site/Project: 898 Joe Frank Harris Pkwy.

Field Dates: October 29, 2021

Field Crew: D. Golden

Scope:

We were requested to locate utilities for the old Kangaroo station.

Site Conditions:

Cool/pavement and grass

Technical approach:

We used a RD8000, Pipehorn 800, and LMX100 GPR.

Records Requested:

None were provided.

Findings:

Water:

We located the water services. There is one water spigot on the Felton Roadside we were unable to locate.

Electric:

We located the electric lines that ran along the property.

Storm:

We located the storm line around the old car wash.

Sewer:

We located the sewer line from the building to the manhole on Felton Road.

Felton Rd

Joe Frank
Harris Pkwy

898
old
Kangaroo
station



ONEVISION
UTILITY SERVICES

PSI/Intertek
898 Joe Frank
Harris Pkwy
October 29, 2021
DFG

